

## Lead in Drinking Water 2020/21

Sample Id#	Initial/Post	Sample Date	Location/notes	Result Rec'd	Actions
<b>1st Flr</b>					
Kit 2 Bay S	2	3/19/2021	left of door by Kitchen Hood	4/8/2021	
Kit Island S	<1	3/19/2021	Island sink in front of Hood	4/8/2021	
Kit Pot	<1	3/19/2021	Large Pot under Hood	4/8/2021	
Kit Ice Mach	<1	3/19/2021	on wall left behind island left	4/8/2021	
WF -7	<1	3/19/2021	hall Water Fountain by 101 B	4/8/2021	
Ice Macine	<1	3/19/2021	Ice Machine in room off 101A girls bath	4/8/2021	
Resource - S	3.3	3/19/2021	resource room Sink in addition	4/8/2021	
Resource - B	7.5	3/19/2021	resource room Bubbler in addition	4/8/2021	
Green R - S	4.5	3/19/2021	green room Sink in addition	4/8/2021	
Green R - B	2.5	3/19/2021	green room Bubbler in addition	4/8/2021	
Yellow R - S	<1	3/19/2021	yellow room Sink in addition	4/8/2021	
Yellow R - B	<1	3/19/2021	yellow room Bubbler in addition	4/8/2021	
Orange R - S	<1	3/19/2021	orange room Sink in addition	4/8/2021	
Orange R - B	2	3/19/2021	orange room Bubbler in addition	4/8/2021	
Blue R - S	<1	3/19/2021	blue room Sink in addition	4/8/2021	
Blue R - B	<1	3/19/2021	blue room Bubbler in addition	4/8/2021	
116 - S1	10.6	3/19/2021	rm 116 Sink 1 (far left, facing outside wall)	4/8/2021	
116-S2	11.8	3/19/2021	rm <b>116</b> Sink <b>2</b> (far right, facing outside wall)	4/8/2021	
116-S3	36.2	3/19/2021	rm <b>116</b> Sink <b>3</b> (near left, facing inside wall)	4/8/2021	Post
116-S4	20.9	3/19/2021	rm <b>116</b> Sink <b>4</b> (near right, facing inside wall)	4/8/2021	Post
115-S1	8.1	3/19/2021	rm 115 Sink middle (cold only)	4/8/2021	
115-S2	5.5	3/19/2021	rm 115 Sink right side	4/8/2021	
WF R	<1	3/19/2021	WF right side in hall by room 111	4/8/2021	
WF L	<1	3/19/2021	WF left side in hall by room 111	4/8/2021	
<b>2nd Flr</b>					
214-S	1.4	3/19/2021	room <b>214</b> Sink	4/8/2021	
212-S	38.6	3/19/2021	Sink in room 212	4/8/2021	Post
212TR-S	<1	3/19/2021	room <b>212</b> nurses office Toilet Room Sink	4/8/2021	
MO-S	Post		<b>Main Office Sink</b>		
MOTR-S	Post		<b>Main Office Toilet Room Sink</b>		
211-TR-S	<1	3/19/2021	hand sink	4/8/2021	
211 S	4.6	3/19/2021	sink on outside wall	4/8/2021	
211-B	out of service		<b>211 Bubbler</b>		
210-S	20.6	3/19/2021	<b>210</b> -hand sink	4/8/2021	Post
210-B	4.7	3/19/2021	<b>210 Bubbler</b>	4/8/2021	
209-S	<1	3/19/2021	<b>209 Sink</b>	4/8/2021	
209-B	out of service		<b>209-Bubbler</b>		
208-S	1	3/19/2021	<b>208- hand sink</b>	4/8/2021	
208-B	out of service		<b>208-Bubbler</b>		
207-S	<1	3/19/2021	<b>207-hand Sink</b>	4/8/2021	
207-B	<1	3/19/2021	<b>207-bubbler</b>	4/8/2021	
206-S	<1	3/19/2021	<b>206-hand sink</b>	4/8/2021	

## Lead in Drinking Water 2020/21

206-B	1.4	3/19/2021	<b>206-bubbler</b>	4/8/2021	
205-S	<1	3/19/2021	<b>205-hand Sink</b>	4/8/2021	
205-B	<1	3/19/2021	<b>205-Bubbler</b>	4/8/2021	
203-S	<1	3/19/2021	<b>203-hand Sink</b>	4/8/2021	
203-B	<1	3/19/2021	<b>203-bubbler</b>	4/8/2021	
202-S	1.2	3/19/2021	<b>202-hand Sink</b>	4/8/2021	
202-B	<1	3/19/2021	<b>202-Bubbler</b>	4/8/2021	
201-S	1.8	3/19/2021	<b>Library 201- toilet roomSink</b>	4/8/2021	
BT - S	<1	3/19/2021	boys toilet sink across 203	4/8/2021	
GT - S	<1	3/19/2021	girls toilet sink across 203	4/8/2021	
WF - 3	out of service		water fountain left across 203		
WF - 4	out of service		water fountain right across 203		
WF - 5	<1	3/19/2021	water fountain across from 211 left side	4/8/2021	
WF - 6	out of service		water fountain across from 211 right side		
BF 2@WF6	<1	3/19/2021	bottle filler @ WF-6	4/8/2021	
221-S	3.3	3/19/2021	Sink	4/8/2021	
218-S	<1	3/19/2021	Sink	4/8/2021	
217-S	2.3	3/19/2021	Sink	4/8/2021	
216-S	4.1	3/19/2021	Sink	4/8/2021	
215-S	3.4	3/19/2021	Sink	4/8/2021	
<b>3rd Flr</b>					
314-S	2.5	3/19/2021	Sink	4/8/2021	
313-S	1.2	3/19/2021	Sink	4/8/2021	
312-S	1	3/19/2021	Sink	4/8/2021	
308-S	1.3	3/19/2021	Sink	4/8/2021	
307-S	<1	3/19/2021	Sink	4/8/2021	
306-S	<1	3/19/2021	Sink	4/8/2021	
305-S	<1	3/19/2021	Sink	4/8/2021	
304-S	<1	3/19/2021	Sink	4/8/2021	
303-S	<1	3/19/2021	Sink	4/8/2021	
302-S	<1	3/19/2021	Sink	4/8/2021	
WF @ T300	<1	3/19/2021	Water fountain @ T200 boys toilet room		
WF 1	out of service		water fountain across 308 left side		
320-S	<1	3/19/2021	Sink	4/8/2021	
319-S	1.1	3/19/2021	Sink	4/8/2021	
318-S	?	3/19/2021	Sink	4/8/2021	
317-S	<1	3/19/2021	Sink	4/8/2021	
316-S	2.3	3/19/2021	Sink	4/8/2021	
315-S	2.6	3/19/2021	Sink	4/8/2021	